


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Run Summary							
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	
D1028-159	Dye	4/22/2009	ADS/TM	S09AA1009MH	Damp	NA	
Address	3606 Copley Road		Location	Curb	Status	Public	Source Catch Basin



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary


Run Summary							
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	
D1028-159	Dye	4/22/2009	ADS/TM	S09AA1009MH	Damp	NA	
Address	3606 Copley Road		Location	Curb	Status	Public	Source Catch Basin

### Observations & Photos

**Obs\_ID** D1028-159-OB01

**Nearest MH** S09AA1009MH

**Comments** Dye observed 3 ft. downstream of S09AA1009MH.  
Infiltration gusher at joint from 10 to 2 oclock.



**Picture** \D1028-159-OB01-P01.jpg

**Comments** 3 ft. downstream of S09AA1009MH along  
S09AA1009G1. Camera rotated 90 degrees  
counterclockwise.